


*IF THE PIPE OUTSIDE DIMETER IS DEEMED INCOMPATIBLE WITH THE SHEAR GUARD COUPLING, OR STAINLEES STEEL FERNCO WITH CONCRETE COLLAR MAYBE SUBSTITUTED AS DETAILED BELOW

SANITARY SEWER OR SERVICE SPOT REPAIR



STAINLESS STEEL FERNCO WITH CONCRETE COLLAR



CITY OF BURNSVILLE - ENGINEERING DEPT.

SANITARY SEWER OR SERVICE SPOT REPAIR

Plate No.	SS-8
Revision Date	1/2018

File Location:

 $S:\ \ Details \land Sanitary \land SS08-Fernco.dwg$